

ATLC Damage From Sunday, December 25 Morning: As of Tuesday, December 27 (11a-2p)

	= No apparent moisture or damage as of 12/27
	= Damp ceiling tile and or carpet, no damage to furnishings/equipment
	= Significant ceiling tile, wet floors, wet furnishings and equipment

Fourth Floor

Fourth Floor Hallway ceiling tile and carpets wet from 404-407, and 410-419

401	CCP Office	
404	Conference Room	Wet carpet at hallway
405	Classroom	Few ceiling tiles and carpet wet near hallway
406	AV Closet	
407	As/400 Computer Lab	
408	As/400 Computer Lab	Damp ceiling tiles in back corner of storage closet
410	PSD Computer Lab	Wet ceiling and floor-removed all computers (Several wet)
412	Video Production Studio	Wet ceiling and floor by door to center of room, with shorted floor electrical outlet. (Furniture and computer dry)
413	Observation Room (Pam Ecker's items stored in plastic)	Wet ceiling and floor by door to center of room (Tubs dry)
414	PSP Computer Lab	Wet ceiling and floor-removed all computers (Several wet)
416	Electrical room	
417	Classroom	Wet ceiling and floor-removed all computers (Several wet) Ceiling projector wet
419	Multimedia computer lab	Wet ceiling and floor-removed all computers (Several wet)
421	Storage	
422	Multimedia computer lab	
424	Equipment repair	
437	John McKamey's Office	
435	Steve Morris' Office	
440	Steffanie Stafford's Office	

Third Floor

Third Floor Floor Hallway ceiling tile and carpets wet from open use computer area across from elevator to 316

313	Classroom	Wet ceiling and floor
Auditorium	Right entrance and top steps only	Wet ceiling tiles to right entrance and top three seating aisles by steps wet.
315	Projection room	
316	Open computer lab	Wet ceiling and floor-removed all computers (Several wet)
317	Open computer lab	
318	Storage	
319	Electrical room	
320	MPC Solutions Computer Lab	
321	Open computer lab	
323	Classroom	
324	Classroom	

Second Floor

Bakery hill dining area wet ceiling tiles and floors

204	Student Activities OK
	Bakery hill behind counter area and kitchen ok
	Career Center OK
	Transfer Center OK
224	Pastry Kitchen OK
231/233	Classrooms OK

First Floor

Overlook dining room nearest to fireplace wet ceilings and floor. Significant damage to overhang from second floor above overlook (Tall ceiling)

Overlook serving areas and kitchens all ok.

Lower Level

Hallway between 0101 Kitch and Welcome Center damp

Welcome center, Instructional Kitchen #001, and Culinary Arts office all OK